



VIPP13-17 DAMPER RED CHANGE


GUIDE




If this is not the damper, check Vipp17 specific.



Unscrew the 2 nuts using a size 7 wrench.




Remove the damper.




The pedal arm has several holes in it. Be sure to locate the correct holes marked.

VIPP13-17 DAMPER RED CHANGE

GUIDE



Make sure to attach the new damper in the holes located previously. Ensure you have the correct angle.



Re-apply the 2 nuts and tighten them.